
TORQUE WRENCHES for "HEX" screws



Why should I use a torque wrench?

While setting a tool it is extremely important to tighten it appropriately. If not effectively tight indeed a cutting tool could slide away from the tool holder during the working process. On the other side, an excessive tightening can cause damages to the tool holder or spring collet or the tool itself.





			Supplied With H=25	LU
ltem	Socket size	Nm	Used on screw	
Z052.771.N	1.3	0,10	Z051.101.R	
Z052.772.N	1,5	0,12	Z051.404.R	
Z052.773.N	2	0,50	Z051.001.R	
Z052.774.N	2,4	0,76	Z051.002.R	
Z052.775.N	4	3,10	Z051.004.R	
Z052.776.N	5	5,00	Z051.016.R	
Z052.785.N	1,6	3,00	Z051.005.R	
Z052.786.N	2,5	5,00	Z051.301.R	
Z052.787.N	3	7,00	Z051.314.R	

Spare parts	Socket size
Z052.771.NCH25	1,3
Z052.772.NCH25	1,5
Z052.773.NCH25	2
Z052.774.NCH25	2,4
Z052.775.NCH25	4
Z052.776.NCH25	5
Z052.785.NCH25	1,6
Z052.786.NCH25	2,5
Z052.787.NCH25	3



How to use

While tightening with constant action a strong shot is perceived both mechanically and acoustically. This indicates that the tightening torque is reached.



www.sistemiklein.com